



**Underwriters
Laboratories Inc.®**

August 30, 2005

Northbrook Division
333 Pfingsten Road
Northbrook, IL 60062-2096 USA
www.ul.com
tel: 1 847 272 8800
fax: 1 847 272 8129
Customer service: 1 877 854 3577

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

Mr. Matthew Davis
ITW Ramset/Red Head
1300 N Michael Dr
Wood Dale IL 60191

E-mail: matt.davis@itw-ramset.com

Reference: File E256323 Project 05CA29289 P.O. Number M DAVIS
USL/CNL - Hole Strap, Cat. Nos. 38HSMP034, 38HSS10, Conduit Clamp, Cat. No.
Product: 12CCMP034L, 34CCMP034L, 12CCSS10L, 34CCSS10L, Threaded Rod Holder, Cat. No.
14TRHMP034, 38TRHMP034, 14TRHSS10, 38TRHSS10

Dear Mr. Davis,

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

Identical to the subject model, which was submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E256323, Volume 1.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E256323, Volume 1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Carnation Ortega

Carnation Ortega
Senior Project Engineer
Department: 3018ANBK
Tel: 847-272-8800
Fax: 847-313-3866
E-mail: carnation.ortega@us.ul.com

Reviewed by:

R. A. Fendrych

Richard Fendrych
Staff Engineer
Department: 3018ANBK

